

General Environmental Incident Summary

Incident: 137 **Date/Time Notice:** 10/15/1991 1000 **DEM Incident No:**

Responsible Party: Army National Guard

Date Incident: 10/7/1991 **Time Incident:** 1100 **Duration:**

County: Burleigh **Twp:** 139 **Rng:** 80 **Sec:** 25 **Qtr:** NE SW

Lat: 46.83073 **Long:** -100.72020 **Method:** Derived from TRS

Location Description: NATIONAL GUARD NEW FACILITY

Submitted By:

Affiliation:

Address:

City:

State:

Zip:

Received By: Gary Reed

Contact Person: Neil Jacobson

Bismarck, ND

Distance Nearest Occupied Building:

Type of Incident: HYDROCARBON

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 50.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: No

Cause of Incident:

LEAK IN HYDRAULIC LIFT. INSIDE NEW BUILDING. REMOVE SOIL.

Risk Evaluation:

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved:

